

SB802

start date	complete date	equip hours	request note	service note	repair subtype	part total	labour total	Total
8/22/2018			REPAIRS @ UNION		R2 External Service	\$ -	\$ -	\$ -
7/10/2018		3453 HR	INSPECTION REPAIRS		R1 Service	\$ 22,679.46	\$ -	\$ 22,679.46
4/16/2018	4/30/2018		INSPECTION REPAIRS	EXTRAS ON ENGINE BY UNION TRACTOR	R1 Service	\$ 70,728.17	\$ -	\$ 70,728.17
4/4/2018	2/16/2018	3309	250 HR SERVICE		R4 Oil Changes	\$ -	\$ 139.28	\$ 139.28
3/30/2018	4/3/2018		PLUNGER ASSEMBLY	REPLACED PLUNGER ASSEMBLY WITH HARWARE,	M3 Hydraulics	\$ 482.36	\$ -	\$ 482.36
3/23/2018	3/23/2018		PUMP PARTS	SEE WORK ORDER FOR DETAILS	M1 Engine	\$ 1,966.55	\$ 406.00	\$ 2,372.55
3/19/2018	3/19/2018		GASKETS	REPLACED GASKETS	M1 Engine	\$ 19.18	\$ -	\$ 19.18
3/12/2018	3/14/2018		LIFT PUMP	NEW GASKET ON THE LIFT PUMP	M3 Hydraulics	\$ 548.38	\$ -	\$ 548.38
3/12/2018	3/14/2018		FUEL PUMP	REPLACED THE FUEL PUMP AS WELL AS NEW GASKETS	M1 Engine	\$ 548.38	\$ -	\$ 548.38
2/10/2018	2/12/2018		MANIFOLD	REPAIRS TO MANIFOLD-GASKETS AND SEALS,	M1 Engine	\$ 995.56	\$ -	\$ 995.56
2/7/2018	2/8/2018		FUEL RATCHET		M1 Engine	\$ 1,427.12	\$ 680.00	\$ 2,107.12
2/3/2018	2/4/2018		COOLANT LEAK		M3 Hydraulics	\$ 556.08	\$ 680.00	\$ 1,236.08
1/24/2018	1/14/2018	3059	1000 HR SERVICE		R4 Oil Changes	\$ -	\$ 201.95	\$ 201.95
9/12/2017	9/12/2017		NUT/BOLT	REPLACE BULLHORN SHEAVE BUSHINGS-INSTAL NEW BOLT-GREASE NIPPLE	M4 Undercarriage	\$ 154.42	\$ 101.50	\$ 255.92
9/9/2017	9/5/2017	2826	250 HR SERVICE		R4 Oil Changes	\$ -	\$ 129.42	\$ 129.42
8/10/2017	8/11/2017		FRONT OIL SEAL LEAK	REPLACED FRONT ENGINE SEAL	M1 Engine	\$ 223.54	\$ 1,218.00	\$ 1,441.54
8/1/2017	7/28/2017		SB802 - INSPECTION REPAIRS UNION	REPAIR OIL PAN, TRANSMISSION PUMP, AND CYL @ UNION TRACTOR	R1 Service	\$ 16,776.59	\$ -	\$ 16,776.59
7/27/2017	7/10/2017	2617	2000 HR SERVICE		R4 Oil Changes	\$ -	\$ 164.30	\$ 164.30
7/24/2017	7/27/2017	2463	FAILED OIL COOLER	REPLACE OIL COOLER	M1 Engine	\$ 1,120.37	\$ 609.00	\$ 1,729.37
3/21/2017	3/21/2017		INCOMING FROM 1701		R1 Service	\$ -	\$ 85.00	\$ 85.00

2/27/2017	2/27/2017		FROM THE GROUND UP MECHANICAL INVOICE	R2 External Service	\$	-	\$	1,870.00	\$	1,870.00	
2/23/2017	2/23/2017		6882651 MANITOBA LTD INVOICE	R2 External Service	\$	-	\$	1,071.00	\$	1,071.00	
2/14/2017	2/14/2017		FROM THE GROUND UP MECHANICAL	R2 External Service	\$	-	\$	4,335.00	\$	4,335.00	
2/13/2017	2/25/2017		FUEL PUMP GOVENER REPAIR	M1 Engine	\$	6,731.51	\$	2,040.00	\$	8,771.51	
2/6/2017	2/6/2017		FROM THE GROUND UP INVOICE	R2 External Service	\$	-	\$	5,865.00	\$	5,865.00	
1/30/2017	1/30/2017		6882651 MECHANICAL REPAIRS	R2 External Service	\$	-	\$	2,040.00	\$	2,040.00	
1/9/2017	2/28/2017		INSPECTION REPAIRS	RECORED RAD AND REPLACED RELIEF VALVE, REPLACED THE WATER PUMP ADAPTER/BEARING AND SEALS, NEW MOUNTING KIT FOR THE FUEL PUMP, NEW CABLE, REPLACED THE VEE BLET, REPLACED MULTIPLE BEARINGS, SEALS AND GASKETS. REPLACED LOCKING LOWER RAILS	R1 Service	\$	20,036.97	\$	-	\$	20,036.97
12/14/2016	12/14/2016		SEAT	R3 Parts & Supplies	\$	452.00	\$	-	\$	452.00	
12/6/2016	2/6/2016		INSPECTION REPAIRS	R1 Service	\$	-	\$	-	\$	-	
11/22/2016	11/28/2016		LOAD LINE BLOCK	M5 Attachments	\$	-	\$	425.00	\$	425.00	
6/24/2016	6/24/2016		TAIL END CLUTCH REPLACE	M5 Attachments	\$	-	\$	1,020.00	\$	1,020.00	
4/6/2016	4/5/2016		INSTALL STICKS AND BLOCKS	M1 Engine	\$	-	\$	255.00	\$	255.00	
4/6/2016	4/5/2016		INSTALL STICK AND RUN- LOAD BLOCKS	M1 Engine	\$	-	\$	170.00	\$	170.00	
3/23/2016	3/21/2016	2482	COMPLETE RETURN INSPECTION	inspection	\$	-	\$	255.00	\$	255.00	

3/6/2016	3/6/2016		Checked complaint of cracked gossetts on C/W : Not cracked. Filled bottom roller with grease.	R1 Service	\$	-	\$	-	\$	-	
2/6/2016	2/6/2016	2334	Remove alternator and install a new bigger one. Modify bracket.	M1 Engine	\$	-	\$	200.00	\$	200.00	
2/5/2016	2/5/2016	2334	Check wiring for charge system.	R1 Service	\$	-	\$	200.00	\$	200.00	
2/4/2016	2/4/2016	2334	Changed tail clutch brake shoe. Adjust rods for tail clutch lever, change batteries, changed alternator.	M1 Engine	\$	-	\$	1,100.00	\$	1,100.00	
2/3/2016	2/3/2016	2327	Charged batteries, checked charging system and changed master switch	R1 Service	\$	-	\$	400.00	\$	400.00	
1/31/2016	1/31/2016	2313		250 hr service. See attached file for details.	R4 Oil Changes	\$	-	\$	-	\$	-
1/21/2016	1/21/2016	11145	Check and adjust clutch. Check for over heating, found fan adjustment bolt out.	M1 Engine	\$	-	\$	400.00	\$	400.00	
1/21/2016	1/21/2016	11145	Check and adjust tail clutch, check for over-heating. Found fan adjustment bolt out.	M1 Engine	\$	-	\$	400.00	\$	400.00	
12/4/2015	12/4/2015	2084	Check PTO sahft, bad yolk to tail clutch.	M5 Attachments	\$	-	\$	400.00	\$	400.00	
11/30/2015	11/27/2015	2065		Performed a 1000hr service. See attachment for details		\$	-	\$	-	\$	-
11/2/2015	11/2/2015	1890	ulled out load line and boom line and checked cables. Check boom kick out.	R1 Service	\$	-	\$	250.00	\$	250.00	

10/23/2015	10/23/2015	885	Installed stump pan	R1 Service	\$	-	\$	100.00	\$	100.00
			Remove driveshaft and							
			replace the rear torque							
			seal. Changed cooland							
10/22/2015	10/22/2015	885	temperature guage,	M2 Powertrain	\$	-	\$	600.00	\$	600.00
			installed new seat							
			cushion, installed floor							
			plates and cleaned out							
			stump pan.							
10/20/2015	10/20/2015	1885	-Changed arm rest	R1 Service	\$	-	\$	100.00	\$	100.00
			Changed trans. Oil Temp							
			guauge and oil pressure							
10/20/2015	10/20/2015	1885	gauge. Removed	M2 Powertrain	\$	-	\$	600.00	\$	600.00
			stumped pan and							
			checked for oil leaks.							
			started inspection,							
9/23/2015	9/23/2015	1885	changed batteries,	R1 Service	\$	-	\$	800.00	\$	800.00
			adjusted brakes, change							
			clutch brake.							
9/17/2015	9/17/2015	1885	Removed floor plates	R1 Service	\$	-	\$	200.00	\$	200.00
			and guards.							
9/16/2015	9/16/2015	1885	start to remvoe plates	R1 Service	\$	-	\$	200.00	\$	200.00
1/31/2015	2/3/2016	1430	CHECK OVER MACHINE		\$	-	\$	450.00	\$	450.00
12/8/2014	12/8/2014	1430	check unit over	M5 Attachments	\$	170.60	\$	1,100.00	\$	1,270.60
12/8/2014	12/8/2014	1430	Machine Inspection		\$	-	\$	600.00	\$	600.00
12/8/2014	12/8/2014	1430	Inspection, Installed		\$	-	\$	600.00	\$	600.00
			stick							
11/15/2014	11/15/2014	1375	check exhaust	M1 Engine	\$	-	\$	200.00	\$	200.00
			remove covers and							
10/11/2014	10/11/2014	1164	panels, remove brake	M5 Attachments	\$	-	\$	900.00	\$	900.00
			bands to unseize lower							
			pin							
TOTAL COST:									\$ 179,177.69	